

UXT Software v4.1.6.7 Release Notes

For UXT-01-002 and UXT-01-004 chips

Released: 6th June 2019

Release Summary

The current and GA software release for Ultimo X chips is v4.1.6.7 (for UXT-01-002 and UXT-01-004 chips).

This is a recommended maintenance release which provides a range of bug fixes.

Note: Make sure you have the latest versions of Dante Firmware Update Manager and Dante Controller. See [Supporting Tools](#) for download links.

New Features

- None (maintenance release)

Issues Fixed

Issue Number	Description
UM-198	sineouttest in the bootloader is broken
UM-779	Make DHCP initial transaction ID a random value
UM-789	Add DDP into the bootloader to UltimoX
UM-78	Improve the failsafe reset counter
UM-45	Device processes set rx/tx channel mute/unmute request and returns success
UM-211	OEM mdns advert causes service registrations to fail
UM-366	Return the Dante domain name via HostCPU DDP
UM-771	Subscriptions fail after reboot / net down using static IP
UM-775	Fix current mode field of DDP message NETWORK_BASIC DDP
UM-776	Return Dante Domain UUID via DDP
UM-777	DDM event notification of device connection state sometimes missing
UM-778	DDP Device erase config message sent when domain membership changes
UM-779	Make DHCP initial transaction ID a random value
UM-786	Improve TX utilisation
UM-788	Make sure UHIP reports TX channel label deletion
ULT-819/UM-166	When an Ultimo device is clock master and is directly connected to another device (not via an outboard switch), if the Ultimo is rebooted, noise occurs on the Tx channels for ~1 second

Issue Number	Description
ULT-371/UM-162	Ultimo is unable to subscribe to a multicast flow if the flow's label length is more than 28 characters, instead the Ultimo will create a unicast flow.
ULT-377/UM-188	If a multicast flow is created on an Ultimo with a label length of more than 19 characters, other devices will be unable to subscribe to the multicast flow, instead devices will subscribe via unicast.
ULT-246/UM-26	After the device friendly name is changed, Dante Device Protocol messages over the SPI or UART may be dropped for ~30 seconds.
UM-274	No Dante Device Protocol "ROUTING_TX_CHAN_CONFIG_STATE" event is sent
UM-784	Improve the fail safe reset counter

Known Issues

Issue Number	Description
ULT-820/UM-229	For Ultimo multicast transmit flows, noise occurs on the Ultimo Tx channels when changing the Ultimo encoding to a higher value (e.g. 16 to 24). Workaround: Unsubscribe receivers from the multicast flow before changing the encoding.
ULT-619/UM-596	DDP_DEVICE_SWITCH_STATUS events are not generated for non-dante ports
UM-780	NETWORK BASIC DDP message is sometimes missing on link up event